

UPPER PROVIDENCE TOWNSHIP SEWER AUTHORITY

935 North Providence Road Media, PA 19063 (P) 610-566-5376 (F) 610-565-8924

August 13, 2025

Operation's Manager's Report to the Upper Providence Township Sewer Authority

1. Grinder Pump Repair and Replacement Costs

The following is a summary of grinder pump and replacement costs for 2025.

	Calls	Total Repair Costs	Total Replacement Costs
2025	120	\$54,617.87 2025 -Budget (\$100,000)	\$326,771.16, 102 Cores 2025 - Budget (\$600,000)

We have 1,689 E-One Grinder Pumps in our System.

2. Incident at 133 Oakview Drive

On July 21, 2025, there was a backup into the home at 133 Oakview Drive which occurred at the same time that our sewer cleaning crews from Wind River / KBX were cleaning the mains.

ServPro was called to the site to remove the effluent water.

We continue to follow up with the property owner and ServPro.