

Site Specific Design, Inc.

**1704 Rockwell Road
Abington, PA 19001
215-887-3730**

Invoice

| Date | Invoice # |
|-----------|-----------|
| 11/5/2021 | 63163 |

| Bill To |
|--|
| Upper Providence Township Attn: Dick Spielman, Sewer Authority 935 N. Providence Road Media, PA 19063 |

| Ship To |
|---|
| Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063 |

| Cust. PO # | Terms | Rep | Ship Date | Ship Via | Ref # | Project |
|------------|--------|-----|-----------|----------|-------|---------|
| | Net 30 | DR | 11/2/2021 | | | |

| Qty | Item Code | Description | Price Each | Amount |
|--|-------------|--|--------------|-----------------|
| | | Repair DH465330 129 Damview Drive Media, PA Date of service 11/2/21 Technician Dylan Rearick Pump running continuously and in high level, station flooded with ground water and seal around plug dirty, cleaned off and lubed with 111 lubricant for better seal against water. Water in eqd, inserts melted. Pulled pump and dry access way emptied into lower chamber. Pump running continuously out of station. Supply cables meg ok. Replaced inserts on both. Pump switches ok, stator melted and contactor popped. Replaced controls and stator and replaced in station. Pump ran normally from alarm to shutoff. Job complete | | |
| 1 | Service/Ins | Service Call & Inspection Fee < | 150.00 | 150.00 |
| 1 | 1265 | CONTROL BRACKET ASM, 240V/60HZ ND0045G01 | 141.83 | 141.83 |
| 1 | 7094 | EQD INSERT, FEMALE (SIX PIN) | 14.7285 | 14.73 |
| 1 | 7095 | EQD INSERT, MALE (SIX PIN) | 15.8195 | 15.82 |
| 2 | Labor-DR | Labor Rate for Dylan Rearick | 51.8225 | 103.65 |
| 1 | 8203RE | Stator/liner assy | 51.8225 | 51.82 |
| All material remains the property of Site Specific Design until final payment. | | | Total | \$477.85 |

**INVOICE REVIEW
UPTSA**

**Okay to PAY
Kevin Matson, PE
12/06/2021**

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.