

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
12/18/2023	73175

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	PB	12/15/2023			
Qty	Item Code	Description			Price Each	Amount
		Replace A151723 with new Twp pump DH862935 Harry L Jordan Jr (Upper Prov) 693 W Baltimore Ave Media, Pennsylvania 19063-3665 Date of service 12/18/23 Technician Pat Brady 12/15/23 Pat arrived on site and found pumpA151723 in alarm and not running all meter readings were incorrect.went to pull pump for further evaluation and found flooded station and a broken lid .Due to the time of day Scott ok To install site spare DH503859.Spare has been installed and pump pumped down and shut off at 5.9 amps pump is running correctly.Will need to return and install new upper providence core and a lid. 12/18/23 Pat Arrived on site to pull sites spare and install upper providence new core and found station was flooded again.Went to take meter readings and there was no power.I knocked in the door and asked homeowner if she could turn power back on spare was pumping but not evacuating station, pulled and found that the grommet				

All material remains the property of Site Specific Design until final payment.

Subtotal
Sales Tax (0.0%)
Total
Payments/Credits
Total Due

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
12/18/2023	73175

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	PB	12/15/2023			
Qty	Item Code	Description			Price Each	Amount
1	Service/Ins	was blown off Installed new core DH862935 pump pump down and off at 5.8 amps pump is running correctly also new lid was installed.			150.00	150.00
4	Labor-PB	Service Call & Inspection Fee < Labor rate for Pat			120.00	480.00
1	9626	9615 Cover kit, replacement lid, D-series, extreme NC0022G05			62.74777	62.75

All material remains the property of Site Specific Design until final payment.

Subtotal	\$692.75
Sales Tax (0.0%)	\$0.00
Total	\$692.75
Payments/Credits	\$0.00
Total Due	\$692.75

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.