

**Site Specific Design, Inc.**

**1704 Rockwell Road  
Abington, PA 19001  
215-887-3730**

**OK TO PAY KMM -  
02-07-2022**

**Invoice**

Date	Invoice #
1/4/2022	63696

Bill To
Upper Providence Township Attn: Dick Spielman, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	PB	12/17/2021			

Qty	Item Code	Description	Price Each	Amount
		Repair DH577383 108 Leedom Dr Media  Date of service 12/17/21 Technician Pat Brady  12/17/21 Arrived on site, dh577383 indicating run dry and not responding to manual run. Power to panel good Pulled pump, Found corroded switches, burnt control bracket, worn cutter wheel, and stator was fine. motor tests fine. Replaced parts and reinstalled pump, would not run. Rechecked wiring and new parts and continued to test, pump will not run. Supply cable from panel fine, tested station with spare and it ran fine. Installed township spare dh5122326 in station. Pump ran at 6.1 amps and shut off successfully. Bringing pump back for inspection, likely has bad supply cable 12/22/21 Pat Pump DH557383 is in shop for Evaluation , and found that the motor windings or bad on the red and black wires . Pump will need To be rebuild or replaced with new core. 12/27/21 Pat Pump DH557383 has been repaired and tested in test tank. Pump goes into and out of alarm, and from on/off 32 seconds at 6.1 amps. Pump is running correctly.		

All material remains the property of Site Specific Design until final payment.

**Total**

**1704 Rockwell Road  
Abington, PA 19001  
215-887-3730**

Date	Invoice #
1/4/2022	63696

Bill To
Upper Providence Township Attn: Dick Spielman, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	PB	12/17/2021			

Qty	Item Code	Description	Price Each	Amount
		Returned to site 12/29/21 and removed township pump DH512326 from station and installed customers pump DH557383 and tested. The pump operates properly. Job complete		
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
4	Labor-PB	Labor rate for Pat	95.00	380.00
1	7290	PRESSURE SWITCH ON/OFF EXTREME w/O-rings NB0083G01	38.185	38.19
1	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings NB0083G02	38.185	38.19
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01	141.83	141.83
1	1203	CUTTER WHEEL, FORGED, MACH/HARDENED NC0008P02 PN 1003	72.006	72.01

All material remains the property of Site Specific Design until final payment.

**Total**

\$820.22

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.