

1704 Rockwell Road
Abington, PA 19001
215-887-3730

Date	Invoice #
9/14/2022	66444

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	DR	8/31/2022			

Qty	Item Code	Description	Price Each	Amount
		<p>DNR DH390122. New Twp pump DH808787 1224 Hunt Club Lane Media, PA 19063</p> <p>Date of service 8/31/22 Technician Dylan Rearick</p> <p>Dh390122 Station in alarm and not running, Pernod thermals out and indicates failed controls. Installed spare and successfully pumped out station, bringing core back to shop for full inspection.</p> <p>ESTIMATE: 09/13/22 Perform meter test on DH390122 and found shorts to ground from pins one and three indicating that the capacitor on control clip had leaked. Removed top housing and inspected the switches and found that they were corroded. Removed control cover and found that the capacitor had exploded and the contactor was burnt. Performed Megan test on motor and it failed on every wire. Removed ground screw and turned the motor on its side and no water came out indicating that the mechanical seal did not fail. The cutter wheel also has no teeth on it. Due to the age of the pump this will most likely be a DNR and replaced with new Township core.</p> <p>9/14/22 Installed dh808787 and collected spare, job complete.</p>		

All material remains the property of Site Specific Design until final payment.

Total

1704 Rockwell Road
Abington, PA 19001
215-887-3730

Date	Invoice #
9/14/2022	66444

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	DR	8/31/2022			

Qty	Item Code	Description	Price Each	Amount
1	Emergency 1 Labor-DR 1 Labor-DR 1 Service/Ins	Returned to investigate alarm. Discharge grommet punched out of discharge, reset and tested, system operates properly now. Emergency Weekend/After Hours Rate Emergency Labor Rate for Dylan Rearick Labor Rate for Dylan Rearick Service Call & Inspection Fee <	165.00 165.00 110.00 150.00	165.00 165.00 110.00 150.00

All material remains the property of Site Specific Design until final payment.

Total

\$590.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.