

Site Specific Design, Inc.

**1704 Rockwell Road
Abington, PA 19001
215-887-3730**

Invoice

Date	Invoice #
9/13/2022	67015

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	DR	9/13/2022			

Qty	Item Code	Description	Price Each	Amount
		Repair Dh433563 Date of service 9/13/22 Technican Dylan Rearick Arrived on site, power to panel good, meter checks indicate failed controls. Pulled Dh433563 and inspected, found corroded switches and burnt motor controls. Motor tests ok not great. Stator and cutter wheel also very worn. Replaced parts and reinstalled pump to test, system operates normally. Job complete		
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
2	Labor-DR	Labor Rate for Dylan Rearick	110.00	220.00
1	7290	PRESSURE SWITCH ON/OFF EXTREME w/O-rings NB0083G01	38.185	38.19
1	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings NB0083G02	38.185	38.19
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01	141.83	141.83
1	8203	STATOR/LINER ASSY EXTREME NC0039G01	51.8225	51.82
1	1203	CUTTER WHEEL, FORGED, MACH/HARDENED NC0008P02 PN 1003	72.006	72.01
All material remains the property of Site Specific Design until final payment.			Total	\$712.04

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.