

Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001

# Invoice

Date	Invoice #
9/23/2022	67196

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	DR	9/23/2022			

Qty	Item Code	Description	Price Each	Amount
		Repair DH402901 110 Kelly Lane Media, PA 19063		
		Date of service 9/23/22 Technician Dyaln Rearick		
		Pump not running, power to panel normal. Replaced corroded switches, burnt control bracket, and worn stator. Pump operates normally.		
1	Labor-DR	Labor Rate for Dylan Rearick	0.00	0.00
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
1	7290	PRESSURE SWITCH ON/OFF EXTREME w/O-rings NB0083G01	38.185	38.19
1	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings NB0083G02	38.185	38.19
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01	0.00	0.00
1	8203	STATOR/LINER ASSY EXTREME NC0039G01	51.8225	51.82

All material remains the property of Site Specific Design until final payment.

**Subtotal** \$278.20

**Sales Tax (0.0%)** \$0.00

**Total** \$278.20

**Payments/Credits** \$0.00

**Total Due** \$278.20

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.