

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001

Invoice

Date	Invoice #
10/7/2022	67417

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	JohnS	10/7/2022			
Qty	Item Code	Description			Price Each	Amount
		Repair DH429213 188 Damview Drive Media, PA 19063 Date of service 10/7/22 Technician John Simons Arrived on site to find station in alarm and panel indicating over pressure. Performed meter test And found shorts to ground on pins one and three and contactor coil showing bad. Removed lid to station and removed DH429213. Inspected the switches and found that they were both corroded. Removed control cover and found that the control clip was completely burnt. Performed Meg test on motor and all readings were correct. Performed ohm check on motor and all readings were correct. Inspected the stater and found egg shells inside of it. Also found that the cutter wheel teeth were worn. Replaced both switches, control clip, stater and cutter wheel. Recommend that no eggshells be put into the system because they will cause premature wear on the pumping mechanism. Returned the pump to station and tested from Alarm. The alarm cleared and the pump cycled and shut off. Perform meter test again and all readings were good. Job complete				

All material remains the property of Site Specific Design until final payment.

Subtotal

Sales Tax (0.0%)

Total

Payments/Credits

Total Due

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001

Invoice

Date	Invoice #
10/7/2022	67417

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	JohnS	10/7/2022			
Qty	Item Code	Description			Price Each	Amount
1	Service/Ins	Service Call & Inspection Fee <			150.00	150.00
1	Labor-JS	Labor rate for John Simons			0.00	0.00
0.5	Labor-JS	Labor rate for John Simons			110.00	55.00
1	Consumables	Includes nuts, bolts, washers, glue, tape, wire nuts, terminal flags, pipe dope, teflon tape, locktite, lubricants			0.00	0.00
1	1203	CUTTER WHEEL, FORGED, MACH/HARDENED NC0008P02 PN 1003			72.006	72.01
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01			0.00	0.00
1	6203	Seal, Level Sensing Housing Extreme NB0043P01			2.18306	2.18
1	7290	PRESSURE SWITCH ON/OFF EXTREME w/ O-rings NB0083G01			38.185	38.19
1	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings NB0083G02			38.185	38.19
1	8203	STATOR/LINER ASSY EXTREME NC0039G01			51.8225	51.82

All material remains the property of Site Specific Design until final payment.

Subtotal	\$407.39
Sales Tax (0.0%)	\$0.00
Total	\$407.39
Payments/Credits	\$0.00
Total Due	\$407.39

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.