

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
11/6/2023	72648

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	BM	11/6/2023			
Qty	Item Code	Description			Price Each	Amount
1		Replace DH486281 with new pump DH869936 Omar Abousoud (Upper Prov) 140 Kingston Road Media, PA 19063 Date of service 11/6/23 Technician Brandon Mauro Arrived on site to find pump DH486281 showing intermittent alarm. Performed meter checks and found 2 shorts to ground on L1-L2 and a bad reading for switches and control bracket. Pulled pump from station and disassembled. I found corroded, pressure, switches, a wornstater, and a burnt double red jumper style control bracket. Also, capacitor had corrosion. Did a meg test on the motor and it had 4 wires in caution. With age of pump being more than 10 years and needing a full rebuild it was replaced core with a new pump DH869936. upper Prov shed does not have cores so they will be billed there set price for core \$2,963.00. Tested new pump and it runs normal time and 5.9 amps consistently. Pump has a far run but still has normal times and alarm functions properly.				
1	Service/Ins	Service Call & Inspection Fee <			150.00	150.00

All material remains the property of Site Specific Design until final payment.

Subtotal

Sales Tax (0.0%)

Total

Payments/Credits

Total Due

**OK TO PAY
KEVIN MATSON, PE,
OPERATIONS MANAGER**


12/04/2023

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
11/6/2023	72648

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	BM	11/6/2023			
Qty	Item Code	Description			Price Each	Amount
2.5	Labor-BM	Labor-Brandon M			120.00	300.00
1	UD200A01A01AA	Core-ug-hw, 240V, CC, 7'C			0.00	0.00
1	Installation of Ne...	Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.			2,963.00	2,963.00

All material remains the property of Site Specific Design until final payment.

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.	Subtotal	\$3,413.00
	Sales Tax (0.0%)	\$0.00
	Total	\$3,413.00
	Payments/Credits	\$0.00
	Total Due	\$3,413.00