

# Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001  
(215) 887-3730



## Invoice

Date	Invoice #
3/14/2024	74413


Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	3/14/2024			

Qty	Item Code	Description	Price Each	Amount
1	UD200A01A01AA	Replace DH428977 with new pump DH884337 Kate Halligan (Upper Prov) 2331 N Feathering Ln Media, Pennsylvania 19063-1966  Date of service 3/14/24 Technician Pat Brady  Arrived on site and found pump DH428977 not in alarm took meter readings and there shorts on all pump Leeds megged cable cable megged good.pulled pump for further evaluation and found bad pump cable installed new core DH884337 ran a hose to the station cycle the pump a couple of times pump pumped down and off at 5.8 amps pump is running correctly.Homeowner has a blockage somewhere from house to the clean out.I showed her there is no water getting into the station.She is calling a plumber	0.00	0.00
		Core-ug-hw, 240V, CC, 7'C		

**OK TO PAY**  
**KEVIN MATSON, PE,**  
**OPERATIONS MANAGER**



**4/8/2024**

All material remains the property of Site Specific Design until final payment.

**Subtotal**

**Sales Tax (0.0%)**

**Total**

**Payments/Credits**

**Total Due**

# Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001  
(215) 887-3730



## Invoice

Date	Invoice #
3/14/2024	74413

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	3/14/2024			

Qty	Item Code	Description	Price Each	Amount
1	Installation of Ne...	Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.	3,111.00	3,111.00

All material remains the property of Site Specific Design until final payment.

**Subtotal** 3,111.00

**Sales Tax (0.0%)** \$0.00

**Total** 3,111.00

**Payments/Credits** \$0.00

**Total Due** 3,111.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.