

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001



Invoice

215-887-3730

Date	Invoice #
4/7/2025	79980

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project			
	Net 30	AD	4/7/2025						
Qty	Item Code	Description			Price Each	Amount			
		Replace DH428418 with new pump DH00939263 Caeser Crogna (Upper Prov) 104 Damview Rd Media, Pennsylvania 19063-1832 Arrived on. Site to find panel in alarm. Performed meter readings and all readings to pump were bad except voltage to pump and panel 240v switches on pump were giving high numbers and I wasn't getting any amp draws. I pulled pump DH428418 and saw that pump was from 01/2012 I replaced with new core that was in the back of my truck new core DH00939263 once I installed pump I ran pump to alarm and I also had customer run water for me so I can run pump to its normal cycle and both times everything checked out good. Amps on new pump is 5.8 amps							
1	Service/Ins	Service Call & Inspection Fee			170.00	170.00			
1	Labor-SGon	Labor rate for Sebastian			130.00	130.00			
1	UD200A01A01AA	Core-ug-hw, 240V, CC, 7'C			0.00	0.00			
						Subtotal			
						Sales Tax (0.0%)			
						Total			
						Payments/Credits			
						Total Due			

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001



Invoice

215-887-3730

Date	Invoice #
4/7/2025	79980

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	4/7/2025			
Qty	Item Code	Description			Price Each	Amount
1	Installation of Ne...	Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.			3,205.00	3,205.00

Subtotal	\$3,505.00
Sales Tax (0.0%)	\$0.00
Total	\$3,505.00
Payments/Credits	\$0.00
Total Due	\$3,505.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.