

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001



Invoice

215-887-3730

Date	Invoice #
5/20/2025	80664

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project			
	Net 30	SGon	5/20/2025						
Qty	Item Code	Description			Price Each	Amount			
		Repair DH00928243 Rachel Benari (Upper Prov) 25 Shady Hill Rd Media, Pennsylvania 19063-4029 Date of service 5/20/25 Technician Sebastian Gonzalez Arrived on site to find pump in alarm. Performed meter readings and I wasn't getting 240v or 120 v in panel went to customers main breakers and flipped it from on to off and on again and then went back to panel and performed meter readings again and I was getting 240v on breakers and on the bottom of breakers and I was getting 120v from neutral to single pole breaker which was good. Only issue I found is that I wasn't getting 120 v from neutral to the yellow wire which was the PCB board. I replaced PCB 9522 with a new one. And flipped breakers back on and noticed that double pole breaker and alarm single pole breaker both made a little spark and some smoke started to come out. I replaced both breakers with new ones and turned them back on and nothing sparked. Continued to performed my meter readings and I was getting 240v in panel and 120v from neutral to yellow.							
						Subtotal			
						Sales Tax (0.0%)			
						Total			
						Payments/Credits			
						Total Due			

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001




Invoice

215-887-3730

Date	Invoice #
5/20/2025	80664

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project			
	Net 30	SGon	5/20/2025						
Qty	Item Code	Description			Price Each	Amount			
		OK TO PAY KEVIN MATSON, PE, OPERATIONS MANAGER							
		 06/09/2025							
1	Service/Ins	Pump readings were all good switches were reading closed I had customer run water for me so I can flood station. Pump also had MCB readings were .074 and amps on pump were running on 5.8 amps. I still pulled pump DH00928243 and checked everything switches were good MCB was in great shape and stator was also in great shape. Installed pump back into station and ran pump to alarm and out of alarm. And was able to run pump to its normal cycle and both times everything checked out good.							
1	Labor-SGon	Job completed							
1	9522	Service Call & Inspection Fee			170.00	170.00			
1	9515	Labor rate for Sebastian PB0939G21 Alarm Replacement PC Board, Simplex Sentry 240/120			130.00	130.00			
1	9504	PB0683P01 2 POLE, 15A, DIN RAIL MT CIRCUIT BREAKER			255.5695	255.57			
		BREAKER, 1 POLE, 15A			61.0827	61.08			
					30.60	30.60			
					Subtotal	\$647.25			
					Sales Tax (0.0%)	\$0.00			
					Total	\$647.25			
					Payments/Credits	\$0.00			
					Total Due	\$647.25			

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.