

# Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001



# Invoice

215-887-3730

Date	Invoice #
5/7/2025	80450

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project			
	Net 30	AD	5/7/2025						
Qty	Item Code	Description			Price Each	Amount			
1	UD200A01A01AA	Replace DH433826 with new pump DH00944038 Terrence Crumlish (Upper Prov) 200 Quiet Hollow Rd Media, Pennsylvania 19063-1009 Date of service 5/7/25 Technician Pat Brady Arrived on site and found pump DH433826 in alarm and not running at all performed meter readings all readings were incorrect pulled pump for further evaluation and found station full of tampons and wipes Pump control housing was heavily corroded and due to age of pump will be installing a new core cleaned out station best i could installed pump DH00944038 pump pumped out of alarm and shut off at 5.9 amps pump is running correctly Core-ug-hw, 240V, CC, 7'C			0.00	0.00			
						<b>Subtotal</b>			
						<b>Sales Tax (0.0%)</b>			
						<b>Total</b>			
						<b>Payments/Credits</b>			
						<b>Total Due</b>			

# Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001



# Invoice

215-887-3730

Date	Invoice #
5/7/2025	80450

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	5/7/2025			
Qty	Item Code	Description			Price Each	Amount
1	Installation of Ne...	Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.			3,205.00	3,205.00
1	Service/Ins	Service Call & Inspection Fee			170.00	170.00
2	Labor-PB	Labor rate for Pat			130.00	260.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.

<b>Subtotal</b>	\$3,635.00
<b>Sales Tax (0.0%)</b>	\$0.00
<b>Total</b>	\$3,635.00
<b>Payments/Credits</b>	\$0.00
<b>Total Due</b>	\$3,635.00