


**KBX Golden**

439 McFarlan Road  
 Kennett Square, PA 19348  
 (610) 444-3551  
 CustomerService@KBXGolden.com  
 www.KBXGolden.com

**INVOICE**

**BILL TO**  
 Upper Providence Township Sewer Authority  
 935 N. Providence Road  
 Media, PA 19063

**INVOICE** 20226229  
**DATE** 06/30/2023  
**TERMS** Net 30  
**DUUE DATE** 07/30/2023

DATE	SERVICE	QTY	RATE	AMOUNT
	15 - Operations & Maintenance Monthly Operations and Maintenance of Pump Stations	1	5,360.69	5,360.69
	MONTH OF JUNE			Subtotal: 5,360.69
	BORTONDALE			
06/07/2023	22 - Premium Time Mechanic Foreman Responded to lag alarm. Upon arrival found lag alarm relay had vibrated out. Reinstalled relay and observed proper operation before departure.	4	139.29	557.16
06/09/2023	22 - Premium Time Mechanic Foreman Responded to lag alarm. Upon arrival, found check valve on side #1 flowing back slightly. Adjusted valve and pushed relay back in position. Observed proper operation before departure.	4	139.29	557.16
06/12/2023	22 - Premium Time Mechanic Foreman Respond to lag and high level alarms during heavy rain event. Observed proper operation before departure.	4	139.29	557.16
06/23/2023	22 - Premium Time Mechanic Foreman Responded to lag alarm. Reset relay, both pumps functioning properly Observed proper operation before departure	4	139.29	557.16
06/27/2023	22 - Premium Time Mechanic Foreman Respond to generator running alarm. Power was out upon arrival. Generator running both pumps operating properly.	4	139.29	557.16
06/27/2023	22 - Premium Time Mechanic Foreman Returned to site upon power restoration. Verified power being restored. Peco notified.	1	139.29	139.29
				Subtotal: 2,925.09
	MEDIA STATION			
06/12/2023	22 - Premium Time Mechanic Foreman Respond to lag and high level alarms during heavy rain event. Observed proper operation before departure.	1	139.29	139.29
				Subtotal: 139.29
	WINTER STREET			
06/14/2023	02 - Mechanic Foreman Respond to call from resident regarding overflowing toilet and alarm sounding at pump station. Mobile dredging was jetting found to be in the area.	2	92.85	185.70

Subtotal: 185.70

ROSE TREE LOWER

06/14/2023	02 - Mechanic Foreman Troubleshoot Bioxide Pump Pump was found not to be working. Contractor will be called into site.	1	92.85	92.85
------------	--	---	-------	-------

Subtotal: 92.85

LETITA LANE

06/22/2023	02 - Mechanic Foreman Arrived on site to trouble shoot pump stations issues. Pump #1 found to have bad meter check and would not run. Pulled pump #1 and installed new pump. Tested new pump and everything functioning properly. Observed proper operation before departure.	1	92.85	92.85
------------	---	---	-------	-------

06/22/2023	Custom Service Contractor's Invoice for pump replacement.		5,444.80	5,444.80
------------	--	--	----------	----------

Subtotal: 5,537.65

---

BALANCE DUE

**\$14,241.27**