

**Site Specific Design, Inc.**

**1704 Rockwell Road  
Abington, PA 19001  
215-887-3730**

# Invoice

Date	Invoice #
11/19/2021	63399

Bill To
Upper Providence Township Attn: Dick Spielman, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	PB	11/18/2021			

Qty	Item Code	Description	Price Each	Amount
		Repair DH486391  99 Springton Lake Rd Media PA 19063  Date of service 11/18/21 Technician Pat Brady  11/18/21 Pat arrived on site and found pump DH486391 in high level alarm. Took meter readings all incorrect, and There is incorrect voltage going to the panel. Pulled pump for further evaluation and found burnt control Bracket, worn cutter, worn Stator, and seal had cloth like material wrapped around it. Repaired pump, and let homeowner know that they need to get an electrician to correct the voltage, also made twp supervisor aware.		
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
2	Labor-PB	Labor rate for Pat	95.00	190.00
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01	141.83	141.83
1	8203	STATOR/LINER ASSY EXTREME NC0039G01	51.8225	51.82
1	1203	CUTTER WHEEL, FORGED, MACH/HARDENED NC0008P02 PN 1003	72.006	72.01
All material remains the property of Site Specific Design until final payment.			<b>Total</b>	\$605.66

**INVOICE REVIEW  
UPTSA**

**Okay to PAY  
Kevin Matson, PE  
12/06/2021**

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.