

**Site Specific Design, Inc.**

**1704 Rockwell Road  
Abington, PA 19001  
215-887-3730**

**Invoice**

Date	Invoice #
12/3/2021	63532

Bill To
Upper Providence Township Attn: Dick Spielman, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	DR	12/2/2021			

Qty	Item Code	Description	Price Each	Amount
		Repair DH507905/DH507854 2105 North Providence Rd Media PA  Date of service 12/2/21 Technician Dylan Rearick  Power to panel good. Pulled pumps one at a time to keep school running.  Dh507901 had worn out cutter wheel and worn stator, switches corroded. Controls and motor fine.  dh507854 also had worn stator, switches, and cutter wheel. Control clip burnt, but motor fine. Replaced parts and reinstalled in station		
1	9615	COVER/GASKET ASSEMBLY (2000)	54.55	54.55
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
3	Labor-DR	Labor Rate for Dylan Rearick	95.00	285.00
2	7290	PRESSURE SWITCH ON/OFF EXTREME w/O-rings NB0083G01	38.185	76.37
2	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings NB0083G02	38.185	76.37
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01	141.83	141.83
2	8203	STATOR/LINER ASSY EXTREME NC0039G01	51.8225	103.65
2	1203	CUTTER WHEEL, FORGED, MACH/HARDENED NC0008P02 PN 1003	72.006	144.01
All material remains the property of Site Specific Design until final payment.			<b>Total</b>	\$1,031.78

**INVOICE REVIEW  
UPTSA**

**Okay to PAY  
Kevin Matson, PE  
12/06/2021**

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.