

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
12/21/2023	73265

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	12/21/2023			

Qty	Item Code	Description	Price Each	Amount
1	UD200A01A01AA	Replace A254023 with new pump DH872811 Ly Chhour (Upper Prov) 449 Old State Road Media, PA 19063 Date of service 12/21/23 Technician Pat Brady Arrived on site and found pump A254023 in Alarm and not running all meter readings were incorrect pulled pump for further evaluation and found roots growing around the inlet of the tank took pictures and sent them to Kevin he asked if I would wait for him to come out he asked for me to leave pump out they are going to try and cut out the roots. Pump A254023 due to the age of the pump Installed new core DH872811 pump pumped down and shut off at 6.3 amps pump is running correctly.	0.00	0.00
		Core-ug-hw, 240V, CC, 7'C		

OK TO PAY
KEVIN MATSON, PE,
OPERATIONS MANAGER


01-08-2024

All material remains the property of Site Specific Design until final payment.

Subtotal

Sales Tax (0.0%)

Total

Payments/Credits

Total Due

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
12/21/2023	73265

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	12/21/2023			

Qty	Item Code	Description	Price Each	Amount
1	Installation of Ne...	Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.	2,963.00	2,963.00
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00

All material remains the property of Site Specific Design until final payment.

Subtotal \$3,113.00

Sales Tax (0.0%) \$0.00

Total \$3,113.00

Payments/Credits \$0.00

Total Due \$3,113.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.