

**Site Specific Design, Inc.**

**1704 Rockwell Road  
Abington, PA 19001  
215-887-3730**

**Invoice**

Date	Invoice #
5/3/2022	65281

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	DR	5/3/2022			

Qty	Item Code	Description	Price Each	Amount
		Repair DH428615 2401 North Feathering Lane, Media, PA. 19063  Date of service 5/3/22 Technician Dylan Rearick  Arrived on site, pump running continuously and in alarm. Pulled and found burnt controls, corroded switches, and worn stator and cutter wheel. Motor tests well, replaced parts and reinstalled, pump functions normally.		
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
1	Labor-DR	Labor Rate for Dylan Rearick	0.00	0.00
1	Labor-DR	Labor Rate for Dylan Rearick	110.00	110.00
1	7290	PRESSURE SWITCH ON/OFF EXTREME w/O-rings NB0083G01	38.185	38.19
1	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings NB0083G02	38.185	38.19
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01	0.00	0.00
1	8203	STATOR/LINER ASSY EXTREME NC0039G01	51.8225	51.82
1	1203	CUTTER WHEEL, FORGED, MACH/HARDENED NC0008P02 PN 1003	72.006	72.01

All material remains the property of Site Specific Design until final payment.

**Total**

\$460.21

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.