

Site Specific Design, Inc.

**1704 Rockwell Road
Abington, PA 19001
215-887-3730**

Invoice

Date	Invoice #
5/4/2022	65299

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	DR	5/4/2022			

Qty	Item Code	Description	Price Each	Amount
1	Service/Ins	Repair DH486389 40 Shady Hill Rd., Media, PA. 19063		
2	Labor-DR	Date of service 5/4/22 Technician Dylan Rearick		
1	8203	Arrived on site. Station not in alarm but pulling high amps. Power levels normal, pulled Dh486389 and found it to be clogged with condoms and tampons. Cleaned out pump and replaced stator and cutter wheel, switches and controls on good working order, and motor tests well. Reinstalled and tested, job complete		
1	1203	Service Call & Inspection Fee < Labor Rate for Dylan Rearick STATOR/LINER ASSY EXTREME NC0039G01 CUTTER WHEEL, FORGED, MACH/HARDENED NC0008P02 PN 1003	150.00 110.00 51.8225 72.006	150.00 220.00 51.82 72.01

All material remains the property of Site Specific Design until final payment.

Total

\$493.83

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.