

Site Specific Design, Inc.

Abington, PA 19001  
215-887-3730

# Invoice

Date	Invoice #
5/24/2022	65532

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	DR	5/24/2022			

Qty	Item Code	Description	Price Each	Amount
		Repair DH506117 Address: 2322 West Deerfield Drive, Media, PA. 19063 (Mary Conroy)  Date of service 5/24/22 Technician Dylan Rearick  Arrived on site, power to panel and meter readings normal, station not in alarm.  Pulled DH506117 and inspected, found corroded switches, everything else normal. Replaced switches and resealed housing with additional grease and retested pump successfully. Job complete.!		
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
1.5	Labor-DR	Labor Rate for Dylan Rearick	110.00	165.00
1	7290	PRESSURE SWITCH ON/OFF EXTREME w/O-rings NB0083G01	38.185	38.19
1	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings NB0083G02	38.185	38.19
All material remains the property of Site Specific Design until final payment.			<b>Total</b>	\$391.38

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.