

Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001  
215-887-3730

# Invoice

Date	Invoice #
7/6/2022	66091

Bill To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063

Ship To
Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via	Ref #	Project
	Net 30	AD	7/6/2022			

Qty	Item Code	Description	Price Each	Amount
		Replace DH393807 with new core dh794986 1204 Hunt Club Lane Media, PA 19063  Date of service 7/6/22 Technician Dylan Rearick  Arrived on site, power to panel good, protect plus panel not running and in alarm. Meter checks indicate failed controls, pulled pump and found bearings worn out and locking up and motor and controls failed testing. Replaced with dh794986 and tested successfully, station pumped out and operating normally again.		
1	Service/Ins	Service Call & Inspection Fee <	150.00	150.00
1	Labor-DR	Labor Rate for Dylan Rearick	110.00	110.00
1	UD200A01A01AA	Core-ug-hw, 240V, CC, 7°C S/N DH794986	0.00	0.00
1	Installation of Ne...	Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.	2,588.00	2,588.00
All material remains the property of Site Specific Design until final payment.			<b>Total</b>	\$2,848.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.