

Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001

# Invoice

Date	Invoice #
10/18/2022	67564

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	DR	10/18/2022			
Qty	Item Code	Description			Price Each	Amount
		Repair Dh424160 231 Appletree Drive Media, PA 19063				
		Date of service 10/18/22 Technician Dylan Rearick				
		Power to panel normal, meter checks normal for flooded station but pump not running. pulled pump and found corroded switches, burnt control bracket, and worn stator. Motor megs and ohms fine. Replaced parts and reinstalled pump in station, job complete.				
1	Service/Ins	Service Call & Inspection Fee <			150.00	150.00
1	Labor-DR	Labor Rate for Dylan Rearick			0.00	0.00
1	Labor-DR	Labor Rate for Dylan Rearick			110.00	110.00
1	7290	PRESSURE SWITCH ON/OFF EXTREME w/O-rings			38.185	38.19
1	7291	NB0083G01				
1	7291	PRESSURE SWITCH, ALARM EXTREME w/ O-rings			38.185	38.19
1	6203	NB0083G02				
1	6203	Seal, Level Sensing Housing Extreme NB0043P01			2.18306	2.18
1	1265	CONTROL BRACKET ASM, 240V/60HZ ND0045G01			0.00	0.00
1	8203	STATOR/LINER ASSY EXTREME NC0039G01			51.8225	51.82

All material remains the property of Site Specific Design until final payment.

<b>Subtotal</b>	\$390.38
<b>Sales Tax (0.0%)</b>	\$0.00
<b>Total</b>	\$390.38
<b>Payments/Credits</b>	\$0.00
<b>Total Due</b>	\$390.38

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.