

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
11/9/2023	72707

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	11/9/2023			
Qty	Item Code	Description			Price Each	Amount
		Replace Dh557362 with new pump DH869944 Eugene Riordan (Upper Prov) 317 Woodland Avenue Media, PA 19063 Date of service 11/9/23 Technician Brandon Mauro Arrived on site to find pump DH557362 indicating alarm and running continuously. Pump was running very low amps and was very loud. Did meter readings and found shorts the ground for L1 and L2. Also, the control bracket reading was wrong. Pop the lid off station and found it was flooded. Removed pump from station and found the stator was completely worn. Both switches were corroded heavily. The cutter wheel has very little teeth left. Bearings of pump were shot and noisy. Control housing of pump was very corroded and rusted. With age of pump and needing a full rebuild, pump was replaced with a new core DH869944. Tested new pump for multiple cycles. New pump runs 5.7 amps and alarm functions properly. Cable good and 9512 board was in good shape. There were no non flushables in station. ** No pumps in upper Prov shed, so I used one I had from our shop that needs			OK TO PAY KEVIN MATSON, PE, OPERATIONS MANAGER  12/04/2023	

All material remains the property of Site Specific Design until final payment.

Subtotal

Sales Tax (0.0%)

Total

Payments/Credits

Total Due

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
11/9/2023	72707

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	11/9/2023			
Qty	Item Code	Description			Price Each	Amount
1	UD200A01A01AA	to be inventoried. Price of pump for Upper Prov is \$2963 plus labor and service fee.**			0.00	0.00
1	Installation of Ne...	Core-ug-hw, 240V, CC, 7'C Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.			2,963.00	2,963.00
1	Service/Ins	Service Call & Inspection Fee <			150.00	150.00
2	Labor-BM	Labor-Brandon M			120.00	240.00

All material remains the property of Site Specific Design until final payment.

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.	Subtotal	\$3,353.00
	Sales Tax (0.0%)	\$0.00
	Total	\$3,353.00
	Payments/Credits	\$0.00
	Total Due	\$3,353.00