

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
3/4/2024	74243

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	JohnS	3/4/2024			
Qty	Item Code	Description			Price Each	Amount
		Replace DH506132 with new twp pump DH880424 Mark Lunden (Upper Prov) 103 Wilton Woods Ln Media, Pennsylvania 19063-1842				
		Date of service 3/4/24 Technician John Simons				
		Arrived on site to find panel not in alarm. Performed meter test and readings were correct. the panel, started to chirp intermittently right in front of me. Removed the lid to Station and pulled DH506132 and found that the cutter wheel has no teeth. The switches are corroded and the control cover is deteriorating. The control bracket is the older style. This pump was manufactured in 2014. Due to the cost of the repairs and the age of the pump, installed new Township core DH880424 and tested from alarm. The alarm sounded properly. Turned on the pump breakers and the pump runs at 5.8 amps. Once the alarm cleared the pump finished its cycle and shut off. Job complete				
1	Service/Ins	Service Call & Inspection Fee <			170.00	170.00
1.5	Labor-JS	Labor rate for John Simons			130.00	195.00

All material remains the property of Site Specific Design until final payment.

Subtotal	\$365.00
Sales Tax (0.0%)	\$0.00
Total	\$365.00
Payments/Credits	\$0.00
Total Due	\$365.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.