

# Site Specific Design, Inc.

1704 Rockwell Road  
Abington, PA 19001



215-887-3730

## Invoice

| Date       | Invoice # |
|------------|-----------|
| 12/19/2024 | 78497     |

| Bill To   |
|---|
| Upper Providence Township<br>Attn: Kevin Matson, Sewer Authority<br>935 N. Providence Road<br>Media, PA 19063 |

| Ship To   |
|---|
| Upper Providence Township<br>935 N Providence Road<br>610-566-5376<br>Media, PA 19063 |

| Cust. PO # | Terms  | Rep | Ship Date  | Ship Via |  | Project |
|------------|--------|-----|------------|----------|--|---------|
|            | Net 30 | AD  | 12/19/2024 |          |  |         |

| Qty | Item Code             | Description  | Price Each | Amount   |
|-----|-----------------------|--|------------|----------|
|     |                       | Replace DH511635 with new pump DH923429<br>555 Rosemary Cir<br>Date of service 12/19/24<br>Technician Pat Brady<br><br>Arrived on site and found pump DH511635 in alarm and not running all meter checks were Incorrect pulled pump for further evaluation and found corroded switches a gassed out capacitor motor megged bad and a worn stator Installed new core DH00923429 pump pumped down and shut off at 6.1 amps pump is running correctly |            |          |
| 1   | UD200A01A01AA         | Core-ug-hw, 240V, CC, 7'C  | 0.00       | 0.00     |
| 1   | Installation of Ne... | Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.   | 3,111.00   | 3,111.00 |

**OK TO PAY  
KEVIN MATSON, PE,  
OPERATIONS MANAGER**

  
01/07/2025

All material remains the property of Site Specific Design until final payment.

**Subtotal** \$3,111.00

**Sales Tax (0.0%)** \$0.00

**Total** \$3,111.00

**Payments/Credits** \$0.00

**Total Due** \$3,111.00

Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.