

### UPTSA January 2024 Pump Station Invoices

#### Upper Prov./Bortondale

Service Date:	Location	Cust#	Jobsite#	Hours	Line item	Price per hour	Tech notes:	Total per WO	WO#
1/8/2024	Upper Prov./Bortondale	2673442	1930598	2	Project-C-Hours-Foreman-Mechanic	95.64	Filled generator with 25 gallons of fuel.	\$191.28	6560001798
1/8/2024	Upper Prov./Bortondale		1930598		Project-C-Materials	132.9	25 Gallons of Fuel	\$132.90	6560001798
1/28/2024	Upper Prov./Bortondale	2673442	1930598	4	Repair-C-Hours-Foreman-Mechanic-OT	143.47	Responded to high water alram due to heavy rain event.	\$573.88	6560002330
1/28/2024	Upper Prov./Bortondale	2673442	1930598	4	Repair-C-Hours-Foreman-Mechanic-OT	143.47	Responded to 2nd high water alram due to heavy rain event.	\$573.88	6560002331
							<b>Pump Station Total</b>	<b>\$1,471.94</b>	

#### Upper Prov/Braves Trail

Service Date:	Location	Cust#	Jobsite#	Hours	Line item	Price per hour	Tech notes:	Total per WO	WO#
1/9/2024	Upper Prov./Braves Trail	2673442	1930600	4	Repairs-C-Hours-Foreman-Mechanic-OT	143.47	Respond to lag and high level alarms. Found side #1 tripped. Reset pump and observed proper operation before departure.	\$573.88	6560001724
1/9/2024	Upper Prov./Braves Trail	2673442	1930600	4	Repairs-C-Hours-Foreman-Mechanic-OT	133	Respond to lag and high level alarms. Found pump #1 wires were burned. Put side #2 in lead. Observed proper operation before departure.	\$532.00	6560001725
1/9/2024	Upper Prov./Braves Trail	2673442	1930600	1	Repairs-C-Hours-Mechanic-OT	133	Respond to lag and high level alarms. Found pump #1 wires were burned. Put side #2 in lead. Observed proper operation before departure.	\$133.00	6560001726
1/17/2024	Upper Prov/Braves Trail	2673442	1930600	1	Repair-C-Hours-Foreman-Mechanic	95.64	Responded to lag alarm. Upon arrival found solenoid blocked and relay had vibrated out of vacuum pump. Cleaned solenoid and put relay back into proper position. Observed proper operation before departure.	\$95.64	6560001944
1/18/2024	Upper Prov/Braves Trail	2673442	1930600	2	Repair-C-Hours-Foreman-Mechanic	95.64	Installed 6 new temporary wires from the feed block to the top of motor breaker #1. The old wires were damaged during a storm. Determined breaker is bad as well. Will need to be replaced.	\$191.28	6560002081
1/18/2024	Upper Prov/Braves Trail	2673442	1930600	2	Repair-C-Hours-Mechanic	88.67		\$177.34	6560002082
1/18/2024	Upper Prov/Braves Trail	2673442	1930600	2	Repair-C-Hours-Mechanic	88.67		\$177.34	6560002083
1/25/2024	Upper Prov/Braves Trail	2673442	1930600	4	Repair-C-Hours-Foreman-Mechanic	95.64	Installed new 100 Amp breaker and wire from block to top of breaker.	\$745.20	6560002172
1/25/2024	Upper Prov/Braves Trail	2673442	1930600		Repair-C-Materials	326.25	Breaker and Wire		
1/25/2024	Upper Prov/Braves Trail	2673442	1930600	4	Repair-C-Hours-Mechanic	88.64	Installed new 100 Amp breaker and wire from block to top of breaker. Cleaned priming system on both pumps and grease pumps.	\$354.68	6560002166
							<b>Pump Station Total</b>	<b>\$2,980.36</b>	

#### Upper Prov/Valley View

Service Date:	Location	Cust#	Jobsite#	Hours	Line item	Price per hour	Tech notes:	Total per WO	WO#
1/16/2024	Upper Prov/Valley View	2673442	1930609	4	Repair-C-Hours-Foreman-Mechanic-OT	143.47	Responded to high water/lag alarm. Upon arrival station operating normally. Cause for alarm unknown. Observed proper operation before departure.	\$573.88	6560001916
							<b>Pump Station Total</b>	<b>\$573.88</b>	

#### Upper Prov./Winters Street

Service Date:	Location	Cust#	Jobsite#	Hours	Line item	Price per hour	Tech notes:	Total per WO	WO#
1/10/2024	Upper Prov./Winters Street	2673442	1930611	1	Repair-C-Hours-Foreman-Mechanic-OT	143.47	Respond to lag alarm. Upon arrival found side #1 thermal tripped. Reset thermal and observed station pumping down. Observed proper operation before departure.	\$143.47	6560001848
							<b>Pump Station Total</b>	<b>\$143.47</b>	

Upper Prov./Toft Woods									
Service Date:	Location	Cust#	Jobsite#	Hours	Line item	Price per hour	Tech notes:	Total per WO	WO#
1/9/2024	Upper Prov./Toft Woods	2673442	1930864	1	Repair-C-Hours-Foreman-Mechanics	95.64	Installed new battery in sensaphone dialer.	\$95.64	6560001727
1/23/2024	Upper Prov./Toft Woods	2673442	1930864	1	Repair-C-Hours-Foreman-Mechanic	95.64	Respond to power failure. Power restored upon arrival. Observed proper operation before departure.	\$95.64	6560002116
1/30/2024	Upper Prov./Toft Woods	2673442	1930864	2	Repair-C-Hours-Foreman-Mechanic	95.64	Responded to a power failure alarm. Power was restored upon arrival. Observed proper operation before departure.	\$191.28	6560002396
							<b>Pump Station Total</b>	<b>\$382.56</b>	