

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
1/23/2024	73699

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	1/23/2024			
Qty	Item Code	Description			Price Each	Amount
		Replace DH433612 with new pump DH879546 Gary Patrick (Upper Prov) 230 East Rose Tree Road Media, PA 19063 Date of service 1/23/24 Technician Pat Brady Home owner said that his basement was backing up and he had a plumber come out .plumber told him there is water down in the station so your pump isn't working .asked him if he lost power and is the alarm going off he said he did lose power but breaks are on in the house.He can't open the panel outside because it's locked .said that he would like service earlier as possible I told him I would be there first thing in the morning Asked if I could be out there by 7:30 1/24/24 Pat Arrived on site and found pump DH433612 not in alarm and not pumping out All meter readings were incorrect.Pulled pump for further evaluation and found station full of grease and motor housing heavily corroded cleaned out station the best I could and Due to age of pump installed new core				

All material remains the property of Site Specific Design until final payment.

Subtotal
Sales Tax (0.0%)
Total
Payments/Credits
Total Due

Site Specific Design, Inc.

1704 Rockwell Road
Abington, PA 19001
(215) 887-3730



Invoice

Date	Invoice #
1/23/2024	73699

Bill To	Ship To
Upper Providence Township Attn: Kevin Matson, Sewer Authority 935 N. Providence Road Media, PA 19063	Upper Providence Township 935 N Providence Road 610-566-5376 Media, PA 19063

Cust. PO #	Terms	Rep	Ship Date	Ship Via		Project
	Net 30	AD	1/23/2024			
Qty	Item Code	Description			Price Each	Amount
1	UD200A01A01AA	DH879546 pump pumped down and off at 6.1 amps. Homeowner still has a blockage somewhere in the house he is going to call a plumber out.			0.00	0.00
1	Installation of Ne...	Core-ug-hw, 240V, CC, 7'C Installation of new Extreme Core w/2 yr warranty. Inspect installation, basin, valve and alarm panel. Inspect EQD & wiring. Remove old pump, identify cause of failure, if possible. Provide warranty documentation. Clean grease and debris accumulation in basin. Install new pump core and test, record performance. Dispose of old components and clean work area.			3,111.00	3,111.00
1	Emergency	Emergency Weekend/After Hours Rate			200.00	200.00
2	Labor-PB	Emergency Labor rate for Pat			225.00	450.00

All material remains the property of Site Specific Design until final payment.

All material remains the property of Site Specific Design until final payment.	Subtotal	\$3,761.00
	Sales Tax (0.0%)	\$0.00
	Total	\$3,761.00
Returned checks will incur a \$25.00 surcharge. If at any time your account runs past due, all shipments may be held pending.	Payments/Credits	\$0.00
	Total Due	\$3,761.00